Tested USB Devices

This includes all devices tested up to and including Pano Suite 2.5.1

TYPE	MAKE	MODEL	NOTES
Test result: Compatible			
Barcode Scanner			
	Metrologic	MS9540	
	POSX	Xi3000	
CD/DVD Drives			
	Hewlett-Packard Company	8200 (USB External CD-RW Drive)	
	IOMagic	IDVD16DDME	
	IOMega	DVDRW20X-U2U	
	LaCie	301230U	
	LG	External Super Multi DVD Rewriter	
	LG Electronics	GCC-5241P (Portable CD-RW/DVD-Rom USB 2.0 Drive)	
	Sony	DRX-840U	
	Sony	MPD-AP20U (Portable USB CD-RW/DVD-ROM)	
Hard Drive			
	Maxtor	EB250G00601 (USB 2.0 250GB OneTouch II Hard Drive)	
	Western Digital Corporation	WD5000D032 (My Book 500GB USB 2.0 Hard Drive)	
Keyboard			
	Compaq Computer Corporation	SDM4540UL (Keyboard: 101 Key USB Style)	
	Dell	SK-8115	
	Dell Computer Corporation	L100 (Keyboard: USB)	
	Hewlett-Packard Company	SK-2506U (USB Keyboard)	
	Kensington	K64370	
	Logitech	Internet 350	
	Memorex	MX2710 (Multimedia USB Keyboard)	
	Microsoft	Comfort Curve Keyboard 2000 (1047)	
	Microsoft	Digital Media Keyboard 3000	
	Microsoft	Digital Media Pro Keyboard	
	Microsoft	KY-0459	
	Microsoft Corporation	RT9401 (Natural Keyboard Pro)	
Keyboard & Mouse Combo			
	Dell	Bluetooth	
	Logitech	Cordless Desktop Wave	
	Logitech	EX110	
	Microsoft	Wireless Laser Desktop 4000 (1045,1058,1028)	
KVM			
	StarView	SV231USB	
Memory Key			

TYPE	MAKE	MODEL	NOTES
Test result: Compatible			
	ATP	ToughDrive 4GB	
	Kingston	DataTraveler II 1GB	
	PNY	2GB	
	PNY	2GB	
	Sandisk	Cruiser Ti	
	SanDisk	SDCZ3-1024-A10 (Cruzer Titanium 1GB 2.0 Flash)	
Mouse			
	Belkin Components	10/19/2007 (Wired USB Mouse)	
	Dell	Basic Optical Mouse	
	Dell Computer Corporation	M/N:M-UAN Del1 (Wired USB Mouse)	
	Dell Computer Corporation	M056U0A (USB Optical Mouse)	
	Fellowes	98905	
	Gateway	MOAKUO (Wired USB 2-Button Optical Scroll Mouse)	
	Hewlett-Packard Company	M-UB48 (USB Mouse)	
	HP	Optical 5-Button Mouse	
	IBM Corporation	M027F0 (Wired USB Optical Wheel Mouse)	
	Kensington Microware Limited	HTB114 (Orbit Trackball 2 Button USB/PS2 Mouse)	
	Lenovo Inc.	25006132 (Wired USB Mouse)	
	Logitech	G9	
	Logitech	M-B7105A	
	Logitech	UAE96	
	Logitech Incorporated	CUAY59B (810-000215) (Wireless USB Laptop Mouse)	
	Logitech Incorporated	M-BA47 (MouseMan Wheel USB1.0/PS2 Mouse)	
	Logitech Incorporated	M-BB48 (MouseMan Wheel USB1.0/PS2 Mouse)	
	Logitech Incorporated	M-RN67 (Cordless USB Mouse)	
	Logitech Incorporated	M-UAN141 (RX 650 Wireless USB Mouse)	
	Microsoft	Basic Optical Mouse	
	Microsoft	Optical 1000	
	Microsoft	Wireless Laser Mouse 5000	
	Microsoft Corporation	X03-46340 (Intellimouse USB 1.1)	
	Microsoft Corporation	X08-71118 (USB Optical Mouse)	
	Microsoft Corporation	X800898-129 (PS2/ USB Basic Optical Mouse)	
	Microsoft Corporation	X800898-132 (Optical Basic 1.0 USB Mouse)	
Multifunction Printer			
	Brother	MFC-8860dn	
	Canon	imageClass MF4270	Installed drivers first, then connected device.
	Epson	Stylus CX7400	
	Epson	Stylus CX8400	
	HP	Photosmart C4280	
	Lexmark International Incorporated	4400-001 (X63 All-In-One USB Printer)	

TYPE	MAKE	MODEL	NOTES
Test result: Compatible			
Music Player			
	SanDisk	m240 (1.GB USB 2.0 Sansa MP3 Player)	
Numeric Keypad			
	Adesso	AKP-150	
PDA			
	Palm	m500	
Printer			
	Canon	IP1800	
	Canon Computer Systems	i475D (Desktop USB Photo Inkjet Printer)	
	Canon Computer Systems	i550 (BubbleJet i550 USB 2.0 InkJet Printer)	
	Canon Computer Systems	i850 (BubbleJet i850 USB 2.0 InkJet Printer)	
	Canon Computer Systems	MF4150 (ImageClass)	
	Epson	LQ-590	
	Epson	Stylus C88+	
	Epson America Incorporated	R300 (Stylus Photo R300 USB InkJet Printer)	
	Hewlett-Packard Company	1018 (USB2.0 Laserjet)	
	Hewlett-Packard Company	3320 (LaserJet 3320 Destop Printer)	
	Hewlett-Packard Company	5150 (DeskJet 5150 USB Inkjet Printer)	
	Hewlett-Packard Company	5610 (OfficeJet USB AiO Printer)	
	Hewlett-Packard Company	C8157A (USB OfficeJet Pro K550 Color Printer)	
	Hewlett-Packard Company	D1455 (USB Deskjet)	
	Hewlett-Packard Company	D2430 (USB Deskjet)	
	Hewlett-Packard Company	D2460 (USB Deskjet)	
	Hewlett-Packard Company	D4160 (USB2.0)	
	Hewlett-Packard Company	D4260 (USB2.0)	
	Hewlett-Packard Company	K8600 (USB2.0)	
	Hewlett-Packard Company	L7580 (USB2.0)	
	HP	Color LaserJet 2605dn	Installed drivers first, then connected device.
	HP	Color LaserJet 2605dn	
	HP	Deskjet 5650	
	Lexmark International Incorporated	15L0000 (USB Z705 Color Jetprinter)	
	Lexmark International Incorporated	18K0286 (USB Z605c Color Jetprinter)	
	Lexmark International Incorporated	4500-101 (E22 Desktop Laser Printer)	
	Lexmark International Incorporated	Z735	
Scanner			
	BizCardReader	600C	
	Panasonic	KV-S1025C	
Serial-to-USB Device			
	Dynex	DX-UBDB9 - 16" USB PDA/Serial Adapter Cable	

TYPE	MAKE	MODEL	NOTES
Test result: Compatible			
Signature Pad			
	Topaz		
Smart Phone			
	Research In Motion	BlackBerry Pearl 8100	
SmartCard/RFID Reader/Fingerprint Reader			
	RFIDeas	RDR-7582AKU	
	Sony	FeliCa RC-S310	
	U.are.U	400B	
USB Hub			
	Adaptec Incorporated	AUH-4000Plus (XHUB4 Plus USB 2.0 Hub)	
	Belkin Components	F5U224 (4-Port USB 2.0 Hub)	
	CP Technologies	CP-UH-135 (4-Port USB 2.0 Plate Series Hub)	
	Dlink	DUB-H7 (7-Port USB 2.0 Hub)	
	IO/Gear	GUH274	
	IOGear	GUH274 (4-Port USB 2.0 Hub)	
Test result: Compatible with issue(s)			
Digital Camera			
	Canon	PowerShot A590IS	Install software first. Rebooted and connected in camera. Device installed successfully but required another reboot.
	Canon, Inc.	A560 (Powershot 7.1MP USB 2.0 Digital Camera)	Supported if it's the only peripheral besides keyboard and mouse.
Foot Pedal			
	Infinity	IN-USB-1	
Hard Drive			
	Archos	40007 (40GB USB 2.0 Mini Hard Drive)	Not enough current to drive the hard drive. This requires a self-powered USB hub.
	Maxtor	Basics 320GB	
	Seagate Corporation	100344194 (2.5 GB USB 2.0 Pocket Hard Drive)	Supported if it's the only peripheral besides keyboard and mouse.
Keyboard			
	Compaq Computer Corporation	SK-2805 (Keyboard: 101 Key USB Style)	May have mouse detection issues if mouse is connected to external hub.
	Dell Computer Corporation	M/N:Y-UK-DEL1 (Wired USB Keyboard)	Keyboard began repeating keys when connected to an external hub.
	Logitech Incorporated	Y-BE22 (Keyboard: USB 1.0 Navigator Keyboard)	When connected to an external hub, this and other devices on the hub failed to be detected on rare occasions.
Memory Key			
	Hewlett-Packard Company	PN657A (256Mb USB 2.0 Flash Drive)	There was a case where the keyboard needed to be unplugged and the virtual machine rebooted before flash was detected.
	Sandisk	Cruzer Titanium 2GB	

TYPE	MAKE	MODEL	NOTES
Test result: Compatible with issue(s)			
Mouse			
	Dell Computer Corporation	M-UK DEL3 (Mouse: USB)	If mouse stops working, it may need to be connected to an external hub.
	Dell Computer Corporation	ODJ301 (USB Mouse)	Installing a printer driver with an attached printer caused a reboot.
	Logitech Incorporated	Mx500 (Mx500 Optical USB Mouse)	
Multifunction Printer			
	Kodak	Easyshare 5500	
Music Player			
	Apple Computer Corporation	M9724LL/A (iPod Shuffle 512MB MP3 Player)	Supported if it's the only peripheral besides keyboard and mouse.
	Apple Computer Corporation	M9804LL/A (iPod Mini 4GB USB 2.0 MP3 Player)	Supported if it's the only peripheral besides keyboard and mouse.
	Apple Computer Corporation	MA099LL/A (iPod Nano 2GB USB 2.0 MP3 Player)	Supported if it's the only peripheral besides keyboard and mouse.
	WIGO CO., Ltd.	CVM100 (256MB USB 1.1 Swing Type MP3 Player)	If device is not detected the first time, unplug it, wait several seconds, then try again.
PDA			
	Palm	Tungsten E2	
Printer			
	Canon Computer Systems	BJC-2110 (BJC-2110 USB Color InkJet Printer)	Supported if it's the only peripheral besides keyboard and mouse.
	Canon Computer Systems	i350 (BubbleJet i350 USB InkJet Printer)	Using an external hub may cause mouse to take longer than usual to be detected.
	Canon Computer Systems	i560 (Desktop USB Photo Inkjet Printer)	Supported if it's the only peripheral besides keyboard and mouse.
	Canon Computer Systems	iP6220D (USB Pixma iP6220D AiO Photo Printer)	Supported if it's the only peripheral besides keyboard and mouse.
	Canon Computer Systems	MP160 (USB Pixma MP160 AiO Photo Printer)	Supported if it's the only peripheral besides keyboard and mouse.
	Canon Computer Systems	MP830 (Pixma Office AiO USB2.0 Inkjet Printer)	May have mouse detection issues if mouse is connected to external hub.
	Epson America Incorporated	B163A (Stylus Photo 820 USB InkJet Printer)	Supported if it's the only peripheral besides keyboard and mouse.
	Epson America Incorporated	C120 (USB2.0 Stylus C120 Color InkJet Printer)	When mouse and printer connected to external hub, the virtual machine may freeze if the external hub is disconnected.
	Epson America Incorporated	RX620 (USB Stylus Photo RX620 Printer)	Supported if it's the only peripheral besides keyboard and mouse.
	Hewlett-Packard Company	D1341	Supported if it's the only peripheral besides keyboard and mouse.
Serial-to-USB Device			
	ATEN/IOGear	UC232A	
Smart Phone			
	Research In Motion	BlackBerry Curve 8310	
Touch Screen			

TYPE	MAKE	MODEL	NOTES
Test result: Compatible with issue(s)			
	ELO	ET1515L-7CWC-1-GY-G	Installed drivers before inserting USB cable. After drivers were installed the cable was plugged in. It was discovered but another reboot was required.
Test result: Incompatible			
CD/DVD Drives			
	Hewlett-Packard Company	8220e (4x4x6 USB External CD-RW Drive)	
Floppy Drive			
	Sony	U3/132	
Hard Drive			
	Western Digital Corporation	WD800B005-RNN (USB 2.0 80GB External Hard Drive)	
Keyboard			
	Apple Computer Corporation	A1048 (Wired USB Keyboard)	Keyboard and mouse stop responding on occasion.
Memory Key			
	ATP	AF1GUFT1BK (1GB USB Flash Drive)	
	Easy Disk	ED717M155A05314 (256MB USB 2.0 Flash Drive)	
	Filemate	N/A (4GB USB 2.0 Flash Drive)	
Mouse			
	Hewlett-Packard Company	265986-003 (Wired USB Optical Scroll Mouse)	
Multifunction Printer			
	Canon	Pixma MP210	
	Lexmark International Incorporated	X1240	System reboots manually when printer driver is installed.
	Lexmark International Incorporated	X9350 (USB2.0 All-In-One W/Duplex Printer)	Printer driver would not install correctly.
Printer			
	Canon Computer Systems	S300 (BubbleJet S300 USB InkJet Printer)	
	Hewlett-Packard Company	6988 (Deskjet Wireless/Network/USB2.0)	The driver required a 32-bit color resolution to install, which the Pano Desktop Service does not support.
	Hewlett-Packard Company	C8970A (USB Deskjet 6940 Color Inkjet Printer)	Printer driver failed to install.
	Hewlett-Packard Company	K5400	
	Hewlett-Packard Company	P2015 (USB2.0)	
	Lexmark International Incorporated	X3470	
Smart Phone			
	Research In Motion	BlackBerry Bold 9000	
SmartCard/RFID Reader/Fingerprint Reader			
	Identix	BT-500	